

	Part Number	Stock Code	Description	Qty
Deburring				
DBT-U	DBT-U	3192-001	Deburring tool for LMR-195 through LMR-600 center conductors	each
Wrenches	WR-600	3190-1435	15/16" box wrench	
	W 1 000	0100 1100	(two required for EZ-600-NMC-2)	each
	WR-900	3190-509	1-1/4" box wrench (two required for	
Printer and the second			EZ-900 connectors)	each
	WR-1200A	3190-512	1-9/16" box wrench (one	
WR-1200A, WR1200B			required for EZ-1200 connectors)	each
	WR-1200B	3190-511	1-7/16" box wrench (one required	aaab
Tool Kits	WR-1700	3190-514	for EZ-1200 connectors) 2" box wrench (two required for	each
	WIN-1700	3130-314	EZ-1700 connectors)	each
			,	
The same of the sa	TK-01	3190-731	Install tool kit for LMR-400/600	
			connectors (includes CCT-02, CST-400,	
200			CST-600, CT-U, .429 and .610 hex dies,	
			tool pouch)	each
	TK-400EZ	3190-1601	Tool kit for LMR-400 crimp	
			connectors (includes CCT-02, CST-400, CT-400/300, tool pouch)	each
	TK-600EZ	3190-1602	Tool kit for LMR-600 crimp connectors	eacii
The state of the s		0.00 .002	(includes CCT-02,CST-600, CT-600,	
			.610 hex dies, tool pouch)	each
5				
Cable End Cutting Tools				
	CCT-02	2102 165	Cable end flush cut tool (pkg of 1)	aaab
A STATE OF THE STA	RB-02	3192-165 3192-166	Replacement blade for CCT-02	each each
	115 02	0.02 .00	Tropiacoment stade for CC1 CC	odon
CCT-02				